

PCP-1072E/1072-2E

Portable Crankshaft Polisher 220V Unit Instructions

GOODSON

Tools and Supplies for Engine Builders

156 Galewski Drive • P.O. Box 847 • Winona, MN 55987-0847
Toll-Free 1-800-533-8010 • Local 507-452-1830 • www.goodson.com

PCP-1072E

PCP-1072-2E

**Please read instructions
before using.**

Warning!

This machine is grounded through the power cord. Use only in a 3 pin, grounded receptacle. Green wire is ground. Black and white are 120V legs

Does not include 3 pin plug. Due to different number of designs available. Contact your electrician for plug recommended in your area

Operating Instructions

1. Install belt over rollers, tighten belt with adjustable roller bracket.

CAUTION: Do not over tighten belts, this will cause belt curling and separation of taped joint. When installing a new belt, run the abrasive over a smooth metal surface for 20 to 30 seconds. This will condition the abrasive grit yielding it not over aggressive.

2. While operating the polisher, 50% of the machine weight should be supported by the operator. Sweep polisher from journal file to opposite file in a slow motion blending finish to a desired quality. Usual polish time per journal is from 10 to 30 seconds depending on journal width.
3. Polishing is always the last operation (other than final cleaning) to the crankshaft. So oil hole champhoring or any other operations should be done previously.

Warning!

Eye protection required while operating this machine!

This machine is grounded through the power plug. **DO NOT** alter this power plug or cord in any way. Personal injury will occur.



PCP-1072E/1072-2E

Pulidor de Cigüeñales

Portable de 220V

por Unidad

Instrucciones

GOODSON

Herramientas y suministros para reconstrutores de motores

156 Galewski Drive • P.O. Box 847 • Winona, MN 55987-0847

Toll-Free 1-800-533-8010 • Local 507-452-1830 • www.goodson.com

PCP-1072E

PCP-1072-2E

Porfavor de leer las instrucciones antes de usar.

AVISO!

Esta maquina es fundado por el enchufe. Use nomas con un pin de 3, receptaculo que es fundado a la tierra. El alambre verde es la conexion a la tierra. Los alambres negros y blancas son los pies de 120V.

Este no incluye el enchufe de 3 pines. Esto se debe a diferente numeros de diseños disponible. Contacta su electricista para escojer un enchufe que es recomendado un su area.



Instrucciones de Operacion

1. Instala la correa sobre las rodillas, apriete la correa con un soporte ajustable para rodilla.

PRECAUCION: No sobre apriete las correas, esto causara que la correa se rize y se separa de el conjunto grabado. Cuando instalando la correa nueva, corre el abrasivo sobre un superficie suave de metal por 20 a 30 segundos. Esto acondicionara la arena del abrasivo para que su rendimiento no se haga agresivo.

2. Cuando operando el pulidor, 50% del peso de la maquina debe ser soportado por un operador. Barre el pulidor de un diario filete al opuesto filete en un movimiento despacion para mezclar el termino para tener la calidad deseada. El comun tiempo para pulir un diario es de 10 a 30 segundos dependiendo del ancho del diario.

3. Puliendo siempre es la operacion ultima(mas que limpiando es ultimo tambien) al cigüeñal. Asi que, el aceitando el hoyo del chmaphoring o cualquier otra operacion se debe hacer antes.

AVISO!

Proteccion de Ojo se necestia cuando operando esta maquina! Esta maquina es fundado por el enchufe. **NO HAGA** alteraciones a este enchufe o cable en cualquiera manera. Heridas personalmente pueden ocurrir.